



Project Guide



Stars 'n' Stripes ▪ votive holder

Glass Cutting: **simple straight lines**

Firings: **full fuse, slump**

Accessories: **tea light**

Step-by-Step

1. Start with 6" clear Blank.
2. Cut two 3" squares from the blue glass and affix at opposite corners of your blank with pinpoints of glue.
3. Cut the white and red Strips into 3" lengths. (If cutting the Strips yourself, make slightly thinner than 1/2" for best fit.) You'll need five or six 3" pieces of each color.
4. Alternate the red and white Strips in the other two corners of your Blank as shown, and affix with pinpoints of glue.
5. Add a white Star CutUp™ on top of each blue square. Place them close to the corners, so they are a focal point after your votive is slumped.
6. Full fuse.
7. Slump over a kiln-washed stainless steel tumbler.
8. Add light!

Variations

- Instead of a CutUp, use triangles to create your star.
- Use coarse Frit to create a "field of stars."

Materials We Used

Blank: 6" clear square

Glass Colors: 132SF Transparent Blue

Strips: 200SF White Opal, 151SF Transparent Cherry Red

CutUps™: two White Stars

Keys to Success

Study a finished votive and notice that the **corners** are most prominent after slumping. This is where you want to place your primary design element.

Note:

Strips = 1/2 x 12" glass strips

Pre-Slumping

